

RECORD OF WORKS CARRIED OUT BY TERRY GRIFFITHS CONTRACTS

PARISH COUNCIL	Ewyas Harold Group Parish Council.
ACCOUNT	Roads.
INVOICE #	TGC1155
MONTH	January 2015

Description of work carried out:-

Specific Tasks.

B4347/C1221junction.

Reported Defect-ref JWS.

Road icing up.

Cleared grids and cleaned out road gullys.

Cleared side entry gullys.

Jet connecting pipes.

Check for areas where water could be getting on to the road other than from blocked drains- none found.

See notes.

C1213.

From 30 MPH limit signs at Ewyas Harold to U74213 junction.

Clear grids and clean out road gullys.

Clear side entry gullys.

Clear pipe drains on bridges.

Jet all connecting pipes.

Jet all road culverts.

Clear headwalls.

Clear grips and reform leads.

Clear drainage washes.

See notes.

U74213.

Little Cym Dulas.

Clear grid and clean out road gullys.

Clear inspection pit.

Jet connecting pipes to outfalls.

Check pedestrian footway over ford.

C1213.

Ewyas Harold- surgery entrance.

Clear grid and clean out road gully.

Clear pit in footway.

Jet connecting pipe to river.

See notes.

B4347.

At junction with C1213.

Clear road grids and clean out road gullys.

Clear side entry gullys.

Jet connecting pipes.

Jet outfall pipe to river.

General.

Collect litter and rubbish from areas worked.

RECORD OF WORKS CARRIED OUT BY TERRY GRIFFITHS CONTRACTS

Notes.

B4347/C1221.

The Parish Council may wish to consider putting a grit bin on this junction if the icing up problem persists.

C1213.

Castle Orchard.

The road gully near this property has a cut of jetter pipe in the outlet pipe. We have made enquiries and confirmed that Amey jetter crew got the pipe jammed and could not retrieve it and it had to be cut and left. In view of this we decided to leave this gully alone for the time being.

C1213.

Doctors surgery.

The main pipe from the pit in the footway to the river is badly silted up and will fail in heavy rainfall. The pipe is oversize for our jetter. With the approval of the PC we will arrange for BBLP jetter crew to attend.

General notes.

C1213.

From Dulas Court to first road bridge in the direction of Longtown.

The ditch on the nearside requires cleaning out and the grips reformed.

C1213.

Bridge at Belpha Farm Entrance.

The storm grid is now blocked completely and requires urgent action.

Have the PC been able to make contact with the landowner and arrange clearing.

U74213.

Little Cym Dulas area.

The ditch on the near side up the hill needs clearing and the grips reforming.