

**RECORD OF WORKS CARRIED OUT BY PARISH LENGTHSMAN**

Date	Description of work carried out
<p><u>Roads</u> <u>Account</u> <u>April 2014</u></p>	<p><u>Priors Field</u> Strim verge along recreation ground hedge. Clear grids and clean out road gulleys. Jet out all connecting pipes.</p> <p><u>B4347</u> <u>Junction with C1213</u> Clear grids and clean out road gulleys. Strim verge to bridge. Strim junction triangle.</p> <p><u>C1219</u> <u>At Pontrilas Merchant entrance.</u> Clear grids and clean out road gulleys. Jet connecting pipes. Clear headwalls - See defect sheet.</p> <p><u>Location at BT poles 1-2</u> Clear grids and clean out road gulleys. Jet to outfall.</p> <p><u>Location at BT pole 5</u> Clear grids and clean out road gulleys. Check outlet pipe clear.</p> <p><u>Junction with U74421</u> Clear grids and clean out road gulleys. Jet connecting pipes. Check outfalls at headwall Strim round waste bins - See defect sheet.</p> <p><u>Rowlestone Village area.</u> Strim verges on junctions and bends. Clear grids and clean out road gulleys. Jet connecting pipes clear. Check culvert headwalls.</p> <p><u>Near Rowlestone House Farm BT pole 3.</u> Locate and clear grid from spring outfall into highway drains. Clear grid and clean out road gulleys. Jet to headwall. Check headwall. Jet out pipe drain to road culvert. See defect sheet.</p> <p><u>Maintenance check on roads.</u> U74413 from C1219 to parish boundary. U74414 from C1219 to junction with U74413. Defects noted for next visit. Please notify us of any known defects on this route.</p> <p><u>General</u> Collect litter and rubbish from all areas worked. Strim round grit bins on routes. Strim round road signs and cut back overgrowth.</p>

Defect Sheet

C1219

At entrance to Pontrilas Merchants.

The ditch and headwall to culverts on the near side in the direction of Rowlestone needs clearing out and the culverts flushed to outfall.

Action - Hereford Highways/BBLP to visit.

Or local team to cost up for funding request to BBLP

N.B. The culvert flushing work would have to be done by BBLP.

At junction with U74421

The ditch and headwall needs clearing out.

On the opposite side of the road to the U74421 there is a large hole which may have been a road drain at some time.

Action - Hereford Highways/BBLP to visit.

Near Rowlestone House Farm BT pole 3

Water is seeping through the road surface causing erosion to tarmac edge. We cannot locate mains water supply pipe in the area.

Action - BBLP to visit.