

RECORD OF WORKS CARRIED OUT BY TERRY GRIFFITHS CONTRACTS

PARISH COUNCIL	Ewyas Harold Group Parish Council.
ACCOUNT	Roads.
INVOICE NO	TGC1144
MONTH	December 2014

Description of work carried out:-

Specific Task.

B4347.

Ewyas Harold.

Woodbine Cottage.

Clear grid and clean out road gully.
Jet blocked pipe to main line.
See notes.

Specific Task.

C1213.

Dulas.

The trout.

Clear grids and clean out road gulleys.
Clear parapet pipe drains
Clear pipe drain.
Jet all connecting pipes to outfalls.
Clear existing grips and reform leads.

Routine maintenance work.

B4347.

From A465 to Morgan's Garage.

Clear grids and clean out road gulleys
Clear side entry gulleys.
Check junction pits clear as required.
Clear kerb drains.
Chip away tarmac blocking entry pipes.
Jet all connecting pipes to outfalls
Clear culvert entry/exits.
See notes.

C1219

Pontrilas.

From junction with A465 to the Ark.

Clear grids and clean out road gulleys.
Jet connecting pipes to outfalls.
Jet road culverts.
See notes.

C1213.

Dulas.

BT post 18.

Locate grid clear and clean out gully.
Jet to field outfall via road culvert.

RECORD OF WORKS CARRIED OUT BY TERRY GRIFFITHS CONTRACTS

C1219.

Rowlestone.

From Rowlestone Court Farm to U74413 junction.

St Michaels Hall.

Clear grids and clean out road gulleys.

Jet connecting to outfalls.

See notes.

Village centre.

Clear drainage trench to junction pit.

Clear headwall grill.

Rowlestone House Farm.

Clear wash to road culvert and jet culvert.

Clear existing grips.

BT post 5.

Clear in filled area of ditch to take water from spring running out into road.

See notes.

Vedw Cottage.

Clear grip and reform lead.

Clear grids and clean out road gulleys.

Jet connecting pipes to stream out fall.

Clear debris blocking double road culvert entry points.

General.

Collect litter and rubbish from areas worked.

Notes.

B4347.

Ewyas Harold.

Woodbine cottage.

We were partly successful in clearing this gully. The water is just about running to the main line drainage. The connecting pipe has possibly been damaged and is restricting flow. We will monitor this drain.

B4347.

Ewyas Harold.

Field between Memorial hall and Morgan's Garage.

The two kerb drains and two road gulleys out fall into a ditch in the field. In places this ditch is blocked or is filled possibly by stock poaching the ground. As this ditch carries water from a number of road gulleys to the river outfall across the main road we could have flooding problems here. No doubt the burden of ownership may fall on the PC/highways as the fall of the field is away from the ditch but it may be worth asking the landowner for some co-operation.

RECORD OF WORKS CARRIED OUT BY TERRY GRIFFITHS CONTRACTS

C1219.

Rowlestone.

St Michaels Hall.

There is a drain pipe on the church side of the hall which is blocked. We have located a pit cover in the verge outside the hall which if opened may allow us to jet back to the blockage.

Could the PC confirm ownership of the verge and secure access for us to lift the cover and complete the clearance work?

C1219.

Rowlestone.

BT post 18.

On the hill Llancillo side the village above the Cym.

We cleared a short distance of this ditch to draw the water from the spring onto the ditch. We need to clear the ditch to the road gully to avoid the road becoming icy.