

RECORD OF WORKS CARRIED OUT BY PARISH LENGTHSMAN

Date	Description of work carried out
<p><u>Roads</u> <u>Account</u> <u>March</u> <u>2014 (1)</u></p>	<p><u>B4347</u> <u>From Ewyas Harold bridge to C1221 junction.</u> Clear grids and clean out all road gulleys (6). Jet connecting pipes clear. Clean out side entry gulleys and jet to main pipe (3).</p> <p><u>C1221</u> <u>From B4347 to Fire Station</u> Clear grids and clean out road gulleys (14.) Jet connecting pipes. Clear side entry gulleys (2). Jet to main pipes.</p> <p><u>From Fire station to Elm Bridge crossing.</u> Clear all existing grips and reform leads. Clear ditch leads. Clear obstructions from ditch.</p> <p><u>Elm Bridge</u> Clear leads to drainage trenches. Clear grid and clean out road gulleys. Jet connecting pipe to river outfall. Re-site overturned grit bin.</p> <p><u>From Elm Bridge to Elm Farm.</u> Clear grids and clean out road gulleys (6). Jet connecting pipes. Locate headwall in field watercourse. Jet road culvert and road gully to headwall. Locate drain pipe in verge - break open to form gully to clear standing water off road on bend.</p> <p><u>From Elm Farm to Parish Boundary - gate 3 at Camp.</u> No drainage system found. Put in grips to clear standing water as required.</p> <p><u>B4347</u> <u>From C1221 junction to parish boundary.</u> Clear grids and clean out road gulleys as required. N.B. As this is a busy road we could only deal with the gulleys at safe areas today. we will arrange traffic management team when servicing remainder of the road gulleys.</p> <p><u>Areywa</u> Partially clear blocked road culvert on bend. Ran out of water for jetter and the light was fading too much to work on this bend.</p> <p><u>General</u> Collect litter and rubbish from all areas worked.</p>

Defect sheet

C1221

Fire Station area.

The ditch on the offside in the direction of Elm Bridge needs cleaning out.

Action - local team to clear subject to Parish Council approval.

In the ditch on the near side in the direction of Elm Bridge there is a private water pipe. This pipe also lies on the verge to a caravan site near Elm Bridge. Local residents state that this pipe is to supply mains water to the site. The pipe will obstruct the cleaning operation and will be damaged by the verge cutter,

Action - Contact BBLP to inspect area.

Elm Bridge Farm area.

The ditch on the near side in the direction of the Camp needs clearing out and the road culvert jettied.

Action - local team to clear subject to Parish Council approval.

N.B. The road gulleys that we attended on this visit were, for the main part, totally blocked and were not functioning. Hopefully in the future they will only need a passing maintenance check.